



Photo #:	001
Date/Time of Photo:	5/19/2014
Photo Location:	Main Dairy
Photo By:	Danielle Block
Photo Description:	Photo taken facing south. Stormwater diversion scrapped of windblown digester solids, silt fences put in place.



Photo #:	002
Date/Time of Photo:	5/19/2014
Photo Location:	Main Dairy
Photo By:	Danielle Block
Photo Description:	Photo taken facing southwest. Tile line in field south east of VTA fixed, channelized flow path from the tile line regraded.



Photo #:	003
Date/Time of Photo:	5/19/2014
Photo Location:	Main Dairy
Photo By:	Danielle Block
Photo Description:	Photo taken facing north east. Grassed waterway north of County Rd C, culvert opposite side to the end of the VTA, was scrapped.



Photo #:	004
Date/Time of Photo:	5/19/2014
Photo Location:	Clyde Hill Facility
Photo By:	Danielle Block
Photo Description:	Earthen berm in place near manure storage.



Photo #:	005
Date/Time of Photo:	5/19/2014
Photo Location:	Clyde Hill Facility
Photo By:	Danielle Block
Photo Description:	Calf hutches moved from the west side of facility.



Photo #:	006
Date/Time of Photo:	5/19/2014
Photo Location:	Clyde Hill Facility
Photo By:	Danielle Block
Photo Description:	Calf hutches moved off of grass on to concrete pad.